

iKON Firmware Version 1.636.0 Release Notes

The latest firmware release for iKON amplifiers includes a number of bug fixes.

Important note: For iKON amplifiers currently on firmware version 1.446.0 or earlier, please contact technical@martin-audio.com for the required interim firmware (1.478.0) and documentation on how to upgrade as a two-step procedure is required.

For devices on 1.510 or later, please upgrade directly to 1.636.0 via the VU-NET software.

Bug Fixes

- Default DSP routing was incorrect
- Default routing for channels 7 and 8 incorrect on iK81

Known Issues

- iKON front panel will sometimes hang during a firmware upgrade. 1.636 will fix this, however during the upgrade to 1.636, the front panel may hang. If this happens, after 10 minutes, power-cycle the unit.