

iKON Firmware Release notes



If your iKONs are running firmware version 1.446 or earlier, the upgrade is a three-step procedure. For instructions and upgrade files, see the software page of our website (go to martin-audio.com and select **Support > Software**).

- Support for Martin-Audio-iKON-Amplifier-Control Q-SYS plugin rev 0.10.



Do not use Q-SYS PLUGIN IK-AMPLIFIER V1.0.

- Fix of an iKON boot issue

Version 1.700 (December 2025)



Make sure you're running Vu-Net 2 version 2.3.3 or later (released December 2025).

Updates

- Added **DevID** (device ID) as the first item in the **Utility** menu. This is for future use.
- Added IP hardware hash filtering to improve network stability for iKONs on high-traffic networks.
- Added automatic protection against Ethernet packet storms. Previously, these storms could cause iKONs to become unresponsive.

Version 1.680 (August 2024)

This firmware fixes a network issue that could damage iKON amplifiers if the control port experienced a packet storm.

Please make sure that amplifier control is on a separate VLAN from Dante and other network traffic. If the iKON control port receives constant non-control data (including Dante), the network card will reboot and the device will temporarily drop off the network. This indicates spurious data is reaching the control port. If this occurs, contact technical@martin-audio.com for assistance in managing your network.

Updates

- Support for iK41.
- New fall-over features (for details, see the Vu-Net 2.3.1 release notes).