

Q-SYS plugin for iKON

Release notes for version 0.10.00.30 (November 2024)

This release includes:

- Support for the iK41.
- Bug fixes to amplifier assignment and status.
- Bug fixes to plugin commands and messages.
- Interface improvements.
- Extra control pins for monitoring output impedance and device current draw. With firmware 1.680, the impedance and current draw are blank. The plugin will display the correct values with a future iKON firmware release.



Don't use Q-SYS PLUGIN IK-AMPLIFIER V1.0 as this version can cause issues.



Make sure you have iKON firmware 1.680 or above. For details, see the **Q-SYS Plugin for iKON User Guide** available from our website [martin-audio.com](https://www.martin-audio.com). Select **Support > Software/Firmware** and scroll to the **Q-SYS Plugin** section.