



## **iKON Firmware Version 1.678 Release Notes**

Firmware version 1.678 for iKON amplifiers includes:

- Support for iK41
- New fall-over features (for details, see the Vu-Net 2.3.0 release notes)
- Support for Martin-Audio-iKON-Amplifier-Control Q-SYS plugin rev 0.05

Note: Don't use Q-SYS PLUGIN IK-AMPLIFIER V1.0

**Important note:** For iKON amplifiers currently on firmware version 1.446 or earlier, the upgrade is a two step procedure. Please contact <u>technical@ martin-audio.com</u> for the required interim firmware (1.478) and documentation on how to upgrade.

For devices on firmware 1.510 or later, you can upgrade directly to version 1.678 using Vu-Net.