

## VU-NET 2.2.3 Release Notes – May 2022

---

The latest release of VU-NET implements new features for iKON amplifiers and DX4.0 controllers.

### Latest Firmware Version

A firmware update for iKON is required to work in conjunction with this version of VU-NET.

- iKON Firmware version – 1.636
- DX4.0 Firmware version – 1.490

### Hardware Support

- Option in routing tab of iKON / DX4.0 to select whether the hardware device is Dante enabled or not. Used when creating offline system designs with iKON / DX4.0. *Note that the option is user editable when in offline mode, but read-only when online as VU-NET detects whether a Dante card is present or not.*
- LED identification function for TORUS products

### Bug Fixes

- Fix to upper value on VX Limiter threshold when bridged output channels are used
- Default input routing fixed for channels A and B
- Dante Lindex MAC address was returning secondary instead of primary value

### Known Issues

- iKON front panel will sometimes hang during a firmware upgrade. 1.636 will fix this, however during the upgrade to 1.636, the front panel may hang. If this happens, after 10 minutes, power-cycle the unit.